Technical Data Sheet

1.0% Palladium On Carbon Extrudate (Size 1-3 mm),(Size 3-5 mm)

Formula	Pd/C Extrudate
Appearance	Black colour free flow extrudate
Metal Loading	0.95% to 1.5%
Active Metal	Palladium
Support Matrix	Carbon Extrudate
Moisture %	Dry

Storage Condition

- Store : Store in a tightly, closed container,
- Atmosphere: Keep in a cool, dry, and well-ventilated indoor storage area away from direct sunlight or dampness.
- Contamination Control: Keep away from sulfur compounds, heavy metals, or dust, which can poison or deactivate the palladium surface.

Application

- Hydrogenation
- Coupling reaction