Technical Data Sheet

0.5% Pd/Coconut Carbon Flakes

Formula	Pd/C flakes
Appearance	Black colour free flow flakes
Metal Loading	0.45% to 0.55%
Active Metal	Palladium
Support Matrix	Carbon flakes
Moisture %	Dry

Storage Condition

- Store : Store in a tightly, closed container,
- Atmosphere: Keep in a cool, dry, and well-ventilated indoor storage area away from direct sunlight or dampness.
- Contamination Control: Keep away from sulfur compounds, heavy metals, or dust, which can poison or deactivate the palladium surface.

Application

- Hydrogenation,
- Debenzylation & Deprotection,
- C-C Bond Formation